

# ADVENTURE!

## HIGH SPEED MACHINING ON A LOW QUALITY MILL



Martin Kennedy  
HMSC – Sept 14, 2013

# HOW THIS ALL STARTED

- ▶ This is what happens when you attend industry trade shows



# FEEDS AND SPEEDS

- ▶ To set speeds & feeds on my CNC mill, I rely mostly on my experience
- ▶ I am very conservative on speeds in general. This is because I've melted several mills.
  - ▶ *Good decisions come from experience. Experience is a result of bad decisions*
- ▶ Speed & feed calculators seem to give:
  - ▶ feeds that are much too high
  - ▶ speeds that are a little too slow

# CALCULATIONS

- ▶ Spindle speed
  - ▶  $Rpm = (CS \times 4) / dia$
  - ▶ For steel & 1/2" mill =  $70 \times 4 / 0.5 = 560 \text{ rpm}$
- ▶ Feed
  - ▶  $Feed = chipload \times n \times rpm$
  - ▶ For steel & 4 flute mill =  $0.005 \times 4 \times 560 = 11 \text{ ipm}$
- ▶ I would never run this fast, even with coolant

# THERE HAS TO BE MORE!

- ▶ Speeds I use for steel with carbide mills
  - ▶ 0.5 – 6 ipm
  - ▶ higher speeds require coolant
  - ▶ Even slower with tool steel mills
- ▶ I was using 0.010 – 0.025” stepover or depth per pass
- ▶ Single milling operations frequently required 45 – 60 minutes
  
- ▶ I wondered if I could do better



# HSM – HIGH SPEED MACHINING


- ▶ Saw a milling center demo at Haas Factory Outlet
  - ▶ ½” carbide mill
  - ▶ Pocket depth 1.5”
  - ▶ Spindle 12,000 rpm
  - ▶ **Feed 160 ipm** (2.7 ips) – operator said could be higher!
  - ▶ Transits 1,000 ipm (16.7 ips)
  - ▶ Tons of coolant
  - ▶ Huge stream of chips flying out of cut
  - ▶ 6” x 6” x 2” chunk of metal mostly cut away in **12 minutes!**
- ▶ I calculated about 4+ hours on my mill, using typical parameters I use

# HSM – HIGH SPEED MACHINING

- ▶ DEFINITION: Achieving **high metal removal** rates with **quick milling passes** using **light milling passes**
  - ▶ Other definitions exist. No consensus on definition
- ▶ In general, incorporates:
  - ▶ High spindle speed (8,000 – 40,000+ rpm)
  - ▶ High feed rates
  - ▶ Unconventional milling patterns
  - ▶ Combined roughing and finishing passes
  - ▶ Less depth passes, up to full depth cuts
  - ▶ Improved accuracy
  - ▶ Longer tool life
- ▶ Concept is from 1920's, but equipment not available then
  - ▶ Rapid progress since 1980, with high speed spindles and CNC
  - ▶ Developed by mold and die industry, cutting hardened materials

# COMPONENTS OF HSM


- ▶ Fast moving small tooling (“small” generally meaning  $\sim 1/2$ ”)
  - ▶ As opposed to large hogging tools
  - ▶ Counterintuitive, but results in higher metal removal rates
- ▶ Low stepover
  - ▶ 5 - 15% of tool diameter
  - ▶ Better chip clearance
  - ▶ Increased mill cooling time
  - ▶ Taking the heat out with the chip
  - ▶ Minimize deflection
- ▶ Specialized G-code
- ▶ Selection of speeds in stable zones that avoid chatter






# MILL LOADING IN CORNERS

- ▶ Conventional milling has  $90^\circ$  mill engagement on straight sections
- ▶ Increases to  $180^\circ$  engagement in corners
  - ▶ Doubles cutter forces
  - ▶ Halves chip clearing
  - ▶ Air cooling halved
- ▶ Feed & speed tables based on allowable in corners



# PATH TO HSM SPIRALING INTO CORNERS


- ▶ Make series of arcs of decreasing radius to cut into corner
- ▶ Allows higher feed rate than conventional corner milling



## PATH TO HSM

# TROCHODIAL MILLING

- ▶ Similar concept to spiraling
- ▶ Applied to slots instead of corners
- ▶ Slots are cut using a series of looping cuts
  - ▶ Faster than a big hogging cutter
- ▶ Techniques:
  - ▶ Loops are more forgiving for slower machines
  - ▶ “D”s require faster machine




MATURING HSM


# CONSTANT TOOL ENGAGEMENT

- ▶ Spiraling and Trochoidal milling are part of HSM (corners and slots)
- ▶ New strategies incorporate both plus strategies to keep tool constantly or uniformly engaged
  - ▶ Available in most major CAM programs
  - ▶ Starting to see in consumer CAM programs
  - ▶ All employ looping toolpaths

# COMPARISON OF TOOL PATHS



Conventional milling path



HSM milling path

# COMPONENTS NEEDED FOR HSM

- ▶ CNC Machine
  - ▶ Preferably built for HSM
    - ▶ High feed rates (1,000 ipm)
    - ▶ High spindle speeds (20,000 rpm)
- ▶ Toolholders
  - ▶ Balanced if speed above 8,000 rpm
- ▶ Cutting tools
  - ▶ High quality carbide, coatings, lubricants, special HSM tools
- ▶ CAM programs
  - ▶ Must be able to create HSM toolpaths
- ▶ Principles of HSM can be applied to lesser machines

# HSM ON A LESSER MILL

- ▶ Chinese Rong Fu mill/drill clone
- ▶ Originally converted to CNC by CNC Masters
- ▶ Control system completely replaced



# TESTING

- ▶ Ran at increasing feed rates using test programs
  - ▶ X transits, back and forth
  - ▶ Y transits, back and forth
  - ▶ Circle transits
  - ▶ Stairstep XY transits
- ▶ Stepper motor would lock up / lose steps at:
  - ▶ X 200 ipm
  - ▶ Y 150 ipm
  - ▶ XY 50 ipm!



# HSM TRIAL 1

- ▶ Simple T-nut design
  - ▶ Speed 45 ipm
  - ▶ Fast transit 150 ipm
  - ▶ Spindle 4,000 rpm
  - ▶ Depth 0.4
  - ▶ Stepover 0.010
  - ▶ Total cut time 4:20
- ▶ 13,500 lines of G-code
- ▶ Crashed on lost steps in fast Y transit
- ▶ Gave me encouragement that it could be done




# TESTING

- ▶ Initial thought was that power supply was inadequate
  - ▶ 4A, 70V
  - ▶ Tried 12A, 60V high quality supply – no change
- ▶ Next thought was that gibs not adjusted correctly
  - ▶ Re-adjusted – little effect
- ▶ Next investigation was into Mach3 parameters
  - ▶ Tried variety of kernal clock rates
  - ▶ Played with stepper motor accelerations


# MODIFIED POWER SUPPLY

- ▶ Beefed up 70V power supply
  - ▶ Added 7,800  $\mu\text{F}$  cap, replacing 1,000  $\mu\text{F}$  cap
  - ▶ Had serial connections for Gecko power. Made “home runs” for each supply line



# STEPPER MOTOR

- ▶ Stepper motors have less torque at higher speeds
- ▶ Y axis carries maximum load – 2 ways, vise, part
- ▶ Tried more powerful stepper motor
- ▶ Increased feed:
  - ▶ X 225 ipm
  - ▶ Y 200 ipm
  - ▶ XY 75 ipm




# HSM TRIAL 2

- ▶ Complex Shape
- ▶ 43,900 lines of G-code
  - ▶ Speed 50 ipm
  - ▶ Fast transit 150 ipm
  - ▶ Spindle 4,000 rpm
  - ▶ Depth 0.3
  - ▶ Stepover 0.010
  - ▶ Total cut time 11:00 v 85:45 conventional
- ▶ Crashed bit at fast Y transit of 150 ipm due to lost steps
  - ▶ That was exciting



# GECKODRIVE STEPPER CONTROLLER

- ▶ Looked at signals to GeckoDrives
  - ▶ Observed step signal jitter on oscilloscope at higher frequency (feed rate) signals
  - ▶ Caused by way Mach3 sends signals
  - ▶ Steppers
    - ▶  $200 \text{ steps/rev} \times 10 \text{ microsteps/step} = 2000 \text{ pulses/rev}$
    - ▶ Ball screws 5 turns/inch  $\Rightarrow 10,000 \text{ pulses/in}$
    - ▶  $200 \text{ ipm} / 60 \text{ sec/min} \times 10,000 \text{ pulses/in} = 33 \text{ kHz pulses/sec}$
    - ▶ Stepper speed is  $200 \text{ ipm} * 5 \text{ turns/inch} = 1,000 \text{ rpm}$



CE RoHS COMPLIANT

# SMOOTHSTEPPER

- ▶ Purchased SmoothStepper
  - ▶ Offloads generation of step signals from computer running Mach3
  - ▶ Dedicated processor for step signals
- ▶ Increased feed rates
  - ▶ X 225 ipm
  - ▶ Y 225 ipm
  - ▶ XY 175 ipm!



# HSM TRIAL 3

- ▶ Cut slots
  - ▶ Speed 50 ipm
  - ▶ Fast transit 125 ipm
  - ▶ Spindle 4,000 rpm
  - ▶ Depth 0.380 and 0.0200
  - ▶ Length x width 1.5" x 1.38" and 3" x 0.85"
  - ▶ Stepover 0.015
  - ▶ Total cut time 4:42 and 7:09
- ▶ **Success, with nice finish and accuracy!**





# QUESTIONS?

